Airport Info

Airport	O69	SNS	MRY		
Clearance					
Ground					
CTAF/Twr	122.7	119.4	118.4		
Departure					
Approach					
Unicom					
Elev	87	85	257		

Check point	NAV ident freq	Dist rem	TC	Wind Dir	Wind Vel	TAS	wca -L +R TH	var -E +W MH	Dist leg	GS est act	Time ETE ATE	Time ETA ATA	Alt
Petaluma Muni	O69			320	15	110					:09		7500
Point Reyes	PYE 113.7			320	15	110					:30		7500
EUGEN	EUGEN			320	15	110					:12		7500
SHOEY	SHOEY			320	15	110					:13		7500
Salinas	SNS 117.3			320	15	110					:00		7500
Salinas Muni	SNS			320	15	110							7500

1. Type	2. Ident	3. Aircraft Type/Equip	4. True Airspeed	5. Departure Point	6. Departure Time proposed	6. Departure Time actual	7. Altitude
vfr / ifr / dvfr	N6483U	M20P/U	110	O69	12:30		7500

8. Route of Flight: V27 SHOEY V230

9. Destination name & city	10. Est time enroute hours	10. Est time enroute minutes	11. Remarks
SNS	1	04	Go Red Sox

12. Fuel on Board hours	12. Fuel on Board minutes	13. Alternate Airport	14. Pilot's name, address, phone #, aircraft base	15. # On Board
5	48	MRY	Edward A. Falk, 600 Fairmont Ave, Mountain View, CA, 650-555-1212, PAO	2
		16. Color of aircraft: white/green	17. Destination contact/telephone (optional): Aunt Abby	

fold

ATIS

Airport	Code	Wind	Ceil/vis	Altimeter	Runway	
Petaluma Muni						
Salinas Muni						
Clearance:	CT					
AD						
Vectors						
Maintain	Expect	In				
Departure	Squawk	Time Off:				

Frequency	Heading	Altitude	

Instructions: Fold form in half. Clip to kneeboard here (with this side face down), leaving other half of page free.